

AIRWORTHINESS DIRECTIVE

88-109/2 Dornier

Date of issue:

24 JAN. 1989

Affected airplane:

German Type Certificate No. 514  
DO 27  
all serials

Subject:

Flight control system, Wing flap position selector

Reason:

Improvement of the longitudinal controllability

Action:

1. Blanking of flap position 45°
2. New marking of airspeed indicator and engine instruments
3. Installing/replacement of placards
4. Supplementation of Flight Manual/Maintenance Manual

All Actions have to be accomplished in accordance with the Service Bulletin.

Compliance:

Within the next 3 months after the effective date of this AD.

Technical publications of the manufacturer:

Dornier Service Bulletin No. 1116-0000 of February 29, 1988 with Revision 2 of September 1, 1988. All serials except H-2 and No. 1123-0000 serial H-2 of April 29, 1988 with Revision 1 of September 1, 1988

which become herewith part of this AD and may be obtained from Messrs. Dornier GmbH, Product Support, D-8000 München 66, Postfach 21 60, Federal Republic of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the airplane's log by a licensed inspector.

Note:

This Airworthiness Directive replaces AD 88-109 of June 8, 1988.